




















RAYTOOLS




RAYTOOLS




-
-
-
-
-
-




RAYTOOLS




(7) Select Similar Figure:




(8) Select Same Figure



(9) Select All Outer Contour



(10) Select All Inner Contour



(11) Select shapes within the specified size

(12) Select Layer

(13) Select By Type


(14) Shear

(15) Copy

(16) Copy with base points

(17) Paste

(18) Delete



(1) Display Open Figure in Red

(2) Display Index (By Part/By Shape)

(3) Display Start Point


(4) Display Cutting Path


(5) Display Travel Path

(6) Display Micro Joint Tag


(7) Check Open Figure



(8) Displays the part fill






- (1) Drawing Import
- (2) Drawing
- (3) Advanced
- (4) Hot Key
- (5) Snap






- (1)
- (2)
- (3)



- (1) Translate
- (2) Zoom
- (3) Align
- (4) Flip Horizontal
- (5) Flip Vertical
- (6) Flip




RAYTOOLS

(7) Rotate CCW90°

(8) Rotate CW90°

(9) Rotate 180°

(10) Rotate



Lead-in and Lead-out Lines Setting

Parameter Setting Of Lead-in And Lead-out Lines
This function is to protect the starting point of parts.


Lead-In	Lead-Out
Type: Line	Type: Nothing
Length: 10 mm	Length: 2 mm
Radius: 2 mm	Radius: 2 mm
Angle: 90 °	Angle: 90 °

☐ On Endpoint ☒ On Long Edge ☐ On StartPoint

☐ works on the outer contour ☐ works on the inner contour
☒ Only Apply to Closed Graphics


☐ Cross Check ☐ Distinguish inner and outer contour

OK Cancel




RAYTOOLS



- (1) Add leadline
- (2) Check Leadlines
- (3) Identify Inner/Outer Contour



- (1) Manual Start Point



(2) Auto Start Point



The screenshot shows a 'Compensation Setting' dialog box with a blue title bar and a close button. The main title is 'Compensation Parameter Setting' with the subtitle 'Cutting slot compensation for graphics.' The dialog is divided into four sections, each highlighted with a red box and a red number:

- (1) The Compensation Parameters:** This section contains three settings: 'Expand Distance' set to 0.1 mm, 'Contract Distance' set to 0.1 mm, and 'Conner treatment' set to Round.
- (2) Common Config:** This section contains two empty dropdown menus followed by the unit 'mm'.
- (3) Way of Compensation:** This section contains four radio button options: 'Outer Expand, Inner Contract' (selected), 'All Expand', 'All Contract', and 'Outer Contract, Inner Expand'.
- (4) Compensation for open figure:** This section contains a checkbox that is currently unchecked.



At the bottom of the dialog, there are three buttons: 'CancelOff', 'OK', and 'Cancel'.

(1) The Compensation Parameters


(2) Common Config

(3) Way of Compensation:

(4) Compensation for open figure:



(1) Manual MicroJoint



(2) Auto MicroJoint

MicroJoint Parameter Setting

Automatic Micro-connection Parameter Setting

Micro-connection is used to insert a non-cutting micro-connection in the track, which can prevent the parts from falling off

Way of MicroJoint

☒ Joint By Count **1**

☐ Joint By Distance

Parameter

Count: 4

Length: 2 mm

☐ Apply Microlength to selected grap...

☐ Micro Joint avoid corner

☐ Joint at Start **2**

☒ Joint by Flycut

☐ Add Leadline at micro joint

Corner Parameter

Safety dist: 5 mm

Maximum angle: 180

Range

Min MicroJoint Graphic Length: 5 mm

Range

3

inner contour ☒ S ☒ M ☒ L

outer contour ☒ S ☒ M ☒ L

SmallContour

Width: 30 Height: 30

BigContour

Width: 1000 Height: 1000

OK Cancel

(1) Way of Microjoint


(2) Parameter



(3) Advanced Options



(4) Corner Parameter

(5) Range


Reverse









(1) Manual Cooling






(2) Auto Cooling Point





RAYTOOLS





Array Parameter Setting

Array Parameter Setting

The graphics is copied quickly according to the set parameters.

RowDis: 20 mm


ColDis: 20 mm

☐ TrueShape

☐ Zero-spacing Array

OK

Cancel



Circular Array

Circular Array Parameter Setting

Draw the graphics as a circular array with a given center.

Array Type

☒ By Quantity 10

☐ By Interval Angle 30

Circular Center

☒ Specified Radius 100

☐ Custom Circular Center

Starting Angle: 0

Angle Range: 360

OK

Cancel

Fly Cut

Fly-cut Parameter Setting

Set a fast cutting process and cutting path for selected graphics.



Fly Cut Mode:	Linear	
Sort Mode:	Bottom to Top	



Starting Position	Bottom Left	
Tolerance	0.1	m
Max Smooth Joint	300	m
Smooth Arc Radius	1	m
☐ Z-Axis not Lift Between Fly Groups		



Laser leads length	0	mm
Laser Lags length	0	mm

OK

Cancel











RAYTOOLS



(1) Smooth Line:



(2) Break Line





(3) Delete Duplicate




(4) Delete Invisible

(5) Merge Line

RAYTOOLS



)
)
)



Circle

3-Point Arc

Scan Arc

Ellipse

Polyline

Polygon

Star

Star

Star

Star-shaped graphic parameter Settings

Fixed-point number:

5

Dist between the center and vertex:

100

mm

Side length:

72.5

mm


Rotation Angle:


0


°

OK

Cancel







Set Part Quantity [X]

Part Number Setting

Set the number of parts and their internal sequencing.

Part Quantity:

☐ Character Recognition

Part Name Settings:

Part identification:

Quantity identification:

Max distance between text an...:

In-part text process:

☒ Internal sort:


☐ Auto change starting point of part

☐ selected shapes are grouped to one part


Tip: Press the Q key to quickly open part settings

OK Cancel


RAYTOOLS



- (1) Quick Access Toolbar
- (2) Part Ba
- (3)



- Delete
- Delete Selected Results
- Delete All Results



- (1) Parameter Setting
- (2) Auto Sorting
- (3) Part Parameter
- (4) Plate Setting:
- (5) Clear the previous nesting results
- (6) Detailed par

The screenshot shows the 'Layout Parameter Setting' dialog box. It has a blue title bar with the text 'Layout Parameter Setting' and a close button. The main title is 'Layout Parameter Setting' with the subtitle 'Set the needed parameters for nesting.' The dialog is divided into several sections: 'Parameter Setting' with a 'Parts Interval' dropdown set to '5 mm'; 'Auto Sorting' with a dropdown set to 'Bottom to Top'; 'Part Parameter' with a radio button for 'All Parts in List'; 'Plate Setting' with radio buttons for 'All Plates In Library', 'Only Selected Plates' (which is selected), and 'Standard Plates', followed by a dropdown menu; 'Length' (1500 mm), 'Width' (3015 mm), 'Number' (30), and 'Plate Margin' (0.1 mm) dropdowns; a checked checkbox for 'Clear the previous nesting results'; and a 'Detailed par' button. At the bottom are 'Cancel', 'Detailed par', and 'OK' buttons.

- (1) Starting Point
- (2) Mirror image
- (3) Nesting Dir
- (4) Best Nesting Direction
- (5) Angle of Rotation
- (6) Inside the hole

(7) Nesting Precision

(8) Merge common edge

(9) All Part Set Grid

(10) All Part Merge common edge

(11) Multiple computation

Detailed parameters

Detailed parameter settings

Setting the relevant parameters of the real shape.

Starting Point

Bottom Left

☐ Mirror image

Nesting Dir

Vertical

☐ Best Nesting Direction

Angle of Rotation

90

☐ Inside the hole

Nesting Precision

0.5

Merge common ed...

C-type2(cut common edge Postpone)

☒ All Part Set Grid



☒ Multiple computation

☐ All Part Merge common edge

OK


Cancel

RAYTOOLS



[illegible][illegible]







[illegible]



[illegible][illegible][illegible]







RAYTOOLS

OK
Cancel
Apply










RAYTOOLS



☐ Auto return after cutting Zero point ▾

☐ EdgeDetect before processing

☐ Perform spot check while run frame Parameter

☒ Re perforation when continuing

Back and forward dist... 2.00mm ▾ 2.00m/min ▾

☒ Process selected o... Manual Speed 12.00m/min ▾
☐ Jog Cut Inching distance 10.00mm ▾



Mark

×

Mark point editing

Name:	X Pos:	Y Pos:	Index
Mark Zero	5.73	37.51	1
Maintenance Pos	100.00	100.00	2
Mark 1	1242.46	1920.02	3
Mark 2	100.00	100.00	4
Mark 3	100.00	100.00	5
Mark 4	100.00	100.00	6
Mark 5	100.00	100.00	7
Mark 6	100.00	100.00	8

Read Curr.Coord.

Save

Cancel



Mark Zero

+

Mark point selecting

×

Mark Zero

Maintenance Pos

Mark 1

Mark 2




Mark 3


Mark 4

Mark 5


Mark 6

Mark point editing






Manual Edge Detection



CCW rotation 9.28 degree, Please note the difference between processing and display


.


- 2-point Edge Detection



- Memory edge detection angle

- Cut off






Machine Coordinate Info

Axis Name	Machine coordi...	Workpiece coord...	Part zero	Follow-up offset
Y	49.48	3.59	45.31	0.00
Y1	49.48	3.59	45.31	0.00
X	47.70	43.09	8.60	0.00
Z	0.00	0.20	0	0.00
F	1.50	0.00	0	0.00

Gantry Single Axis Test

Motor enable and disable


Y axis


Y1 axis

Single axis fixed pulse motion test

X-axis encoder:13251.11, Y-axis encoder:13743.11, Y1-axis encoder:13743.11, Y-Y1=0.00

☐ Positive
☒ Negative

Clear

Y Axis

0

Pulses

Send

Hardware Info

Slave station order	Slave station name	Op Status	P0-Crc	P0-PHY	P1-Crc	P1-PHY	P2-Crc	P2-PHY
0	CDHD	OP	0	0	0	0		
1	CDHD	OP	0	0	0	0		
2	CDHD	OP	0	0	0	0		
3	ES100N_V0.4	OP	0	0	0	0		
4	EDS2000V3.3(XFC)	OP	0	0				

Master0

Phase: Operation

Active: yes

Slaves: 5

Ethernet devices:

Main: 00:e0:00:01:a3:a0 (attached)

Link: UP

Tx frames: 1766342



Tx bytes: 624298412



Rx frames: 1766341

Rx bytes: 624298060

Reset Salve Register









[illegible][illegible]

[illegible][illegible]



-
-
-
-



MachineOverviewWindow

Machine structure

TypeDual drive

Master slave stop s...1

Verticality correctionDisable

Dust removal valveOpen

Laser parameter

BrandIPG

Master-Slave Axes...Reverse

Max offset in Mest10

Frequency50000.00

Authorization period

2024-04-11~Permanent

Height sensor

Type1

Power rating1000.00

Follow max height

Pallet Changer Control

Pallet changerOpen

TypeParallel

X Axis

Encoder pulse num...10000.00

Pitch36

Motor directionPositive

Homing ModeIncremental M...

Return to origin sig...Limit

Zero signal logicNO

Limit-0.00

Limit+1500.00

Pitch compensationDisable

Y Axis

Encoder pulse num...10000.00

Pitch36

Motor directionPositive

Homing ModeIncremental M...

Return to origin sig...Limit

Zero signal logicNO

Limit-0.00

Limit+3000.00

Pitch compensationDisable

Z Axis

Encoder pulse num...10000.00

Pitch10

Motor directionPositive

Homing ModeIncremental M...

Return to origin sig...Limit+

Zero signal logicNO

Limit-100.00

Limit+2.00

Focus control

Cut headUnKnown BS...

Focus adjmt. axis...12

Max positive focus17.00

Min negative focus-17.00

Cutting Type

FlyCut TypePLC Control

Fine Tune0.08

Fine Tune0.8

MicroJoint TypePLC Control

Version

HMI1.0.0.32427

PLC32257.0


CNC16940447

NC2.10.78643489

CAM1.0.0.32337

Engine23734

Config Tool2.4.3.32222



-
-
-
-

Drawing

System

Alarms

(08/13 14:52:33.859) Operation by software button on HMI: ZAxis stop moving in manual mode

(08/13 14:55:35.228) Manual slow

(08/13 14:55:35.231) Move left

(08/13 14:55:35.360) Stop

(08/13 14:55:35.827) Manual slow

(08/13 14:55:35.828) Move left

(08/13 14:55:36.029) Manual slow

Drawing

System

Alarms

2024/8/13 14:55:42 Have select 2 object.Size: 12 x 12

2024/8/13 14:55:44 Delete Selected Graphics,Press E button delete.

2024/8/13 14:55:45 Draw Rectangle and Specify First AngularPoint:

2024/8/13 14:55:46 (2.518,54.815)

2024/8/13 14:55:46 Draw Rectangle and Specify another AngularPoint(or Size(D)):

2024/8/13 14:55:46 (10.474,48.739)

2024/8/13 14:55:46 Have select 1 object.Size: 7.957 x 6.076

Drawing

System

Alarms

(08/13 14:52:33.859) Operation by software button on HMI: ZAxis stop moving in manual mode

(08/13 14:55:35.228) Manual slow

(08/13 14:55:35.231) Move left

(08/13 14:55:35.360) Stop


(08/13 14:55:35.827) Manual slow

(08/13 14:55:35.828) Move left

(08/13 14:55:35.935) Stop

(08/13 14:55:36.029) Manual slow

Drawing		Custom	Alarms	Fine Tune		0.001mm
		Time	ID	Status	Description	
Alarm Reset	20240813 14:52:23	20000	Inactive	Axis is not enabled, please click the "enable" button of PM1 to enable the axis.		
	20240813 14:52:23	889	Active	The system is in debugging state. In this mode, follow up related operation is disabled.		
	20240813 14:52:26	1118	Active	The pallet is not in place, the automatic clamping and loosening of the starting cylinder failed!		
	20240813 14:52:26	150	Active	Open the function of OFF_Follow		



-
-
-

Count Manager

Count Manager

Set parameters of production statistics, machining quantity and auto pause, etc.

Count Manager

Total0.00

Finished55.00

Aft task doneStand still

Stand still

Popup prompt

Forbid start again

Pause Count

Clear

Cancel

Change PWD

OK

-
-
-
-
-